

DEPARTMENT OF TRANSPORTATION**DIVISION OF ENGINEERING SERVICES**

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-024938**Date Inspected:** 25-Apr-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Xu Le Feng /Qiu Wen**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG Bike Path**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector, Scott Leavitt, was present during the times noted above for observations relative to the work being performed.

Bay 10 – Tower Shop

In Process Inspection SMAW

This QA Inspector observed the following work in progress: SMAW welding of weld joint 001 located on X3305K-019. Welder is identified as 500363. ZPMC Quality Control (QC) is identified as Qui Wen. The welding variables recorded by QC appeared to comply with the Applicable WPS.

This QA Inspector observed the following work in progress: SMAW welding of weld joint 002 located on X3305K-020. Welder is identified as 040582. ZPMC Quality Control (QC) is identified as Qui Wen. The welding variables recorded by QC appeared to comply with the Applicable WPS.

This QA Inspector observed the following work in progress: SMAW welding of weld joint 016 located on BK010ASD1-001. Welder is identified as 053829. ZPMC Quality Control (QC) is identified as Qui Wen. The welding variables recorded by QC appeared to comply with the Applicable WPS.

Visual Inspection

The following Non Destructive Testing (NDT) inspection carried out as per the ZPMC submitted Notification No 08926.

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

This QA inspector performed VT of an area that has been previously tested and accepted by ZPMC Quality Control (QC) personnel.

The members are identified as:

31TR3-001-038, 039, 042, 043
31TR3-001-046, 035, 041
31TR3-001-045, 040, 034
31TR1-001-004, 008, 011
31TR1-001-002, 013, 016
31TR1-001-006, 007, 009, 010
31TR2-001-018, 030, 025
31TR2-001-022, 023, 026, 027
31TR2-001-020, 024, 029

The following Non Destructive Testing (NDT) inspection carried out as per the ZPMC submitted Notification No 08930.

This QA inspector performed VT of an area that has been previously tested and accepted by ZPMC Quality Control (QC) personnel.

The members are identified as:

BK014A2-001-013, 021, 002, 008
BK014A2-001-014, 015, 017, 019, 020
BK014A6-001-173, 174, 175, 176

Magnetic Particle Inspection (MT)

The following Non Destructive Testing (NDT) inspection carried out as per the ZPMC submitted Notification No 08926.

This QA inspector performed MT of approximately 15% of an area that has been previously tested and accepted by ZPMC Quality Control (QC) personnel. This QA Inspector generated an MT report for this date.

The members are identified as:

31TR3-001-038, 039, 042, 043
31TR3-001-046, 035, 041
31TR3-001-045, 040, 034
31TR1-001-004, 008, 011
31TR1-001-002, 013, 016
31TR1-001-006, 007, 009, 010
31TR2-001-018, 030, 025
31TR2-001-022, 023, 026, 027
31TR2-001-020, 024, 029

The following Non Destructive Testing (NDT) inspection carried out as per the ZPMC submitted Notification No 08930.

This QA inspector performed MT of approximately 15% of an area that has been previously tested and accepted by ZPMC Quality Control (QC) personnel. This QA Inspector generated an MT report for this date.

The members are identified as:

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

BK014A2-001-013, 021, 002, 008

BK014A2-001-014, 015, 017, 019, 020

BK014A6-001-173, 174, 175, 176

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.



Summary of Conversations:

No relevant conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang at 15000422372, who represents the Office of Structural Materials for your project.

Inspected By: Leavitt, Scott

Quality Assurance Inspector

Reviewed By: Clifford, William

QA Reviewer
